

Klient. - Kontrolní list

Datum: 3.2. 2014

Kontrola provedena od do Hod,

KM.....

NEUMANN 1

Kontrolor: VAVŘOLA

Materiál: COMFOR
V. NOVÁK 9

SČ/ID rajon/Okre	Obec	Ulice	Č. p.	Č. p.	Č. p.	Typ domu	Zjištění			Výsledek měření	Poznámka
							1	2	3		
1		MAKA	58			R	A			A	
2		-4-	40			R	A			A	
3		DÍŠTINŮ	3			L	A			A	
4		-4-	52			R	A			A	
5		-4-	19			R	A			A	
6		DOL. LHOTA	41			R	A			A	
7		-4-	42			R	A			A	
8		-4-	39			R	A			A	
9		STRAŽ/ N.	129			R	A			A	
10		-4-	250			R	A			A	
11		-4-	234			R	A			A	
12		-4-	4	R		R	A	A		A	
13		-4-	42			R	A			A	
14		-4-	260			R	A			A	
15		MAKA	11			R	A			A	
16		NOVOSEDLY/ N	191			R	A			A	
17		-4-	22			R	A			A	
18		-4-	44			R	A			A	
19		-4-	96			R	A			A	
20		-4-	120			R	A			A	
21		KLEČ	76			R	A			A	
22		-4-	56			R	A			A	
23		-4-	23			R	A			A	
24		-4-	84			R	A			A	
25		LOMNICE/ L	299	449	BEČOV	R	A	N		A	
26		-4-	569			R	A			A	
27		-4-	535			R	A			A	
28		FRANĚLŮ	6			R	A			A	
29		-4-	14			R	A			A	
30		-4-	43			R	A			A	
Celkový výsledek v %:			96,15			Počet ANO:			29		

PODPIS:

PODPIS:

PODPIS:
RAZÍTKO

Razítko